

Subject: PROTECTOR FLAME SAFETY LAMP SERVICE UPDATE 3 - 31 MARCH 2009

From: david mather <dmath@protectorlamp.com>

Date: Tue, 31 Mar 2009 16:54:30 +0100

To: andrew.watson@minerescue.com, blee@ukcoal.com, Charlie Smith <charlie.smith@powerfuel.plc.uk>, dvernon@ukcoal.com, eruck@ukcoal.com, gpotter@ukcoal.com, ian.asquith@maltbycolliery.co.uk, johannetts@ncm.org.uk, nbattison@ukcoal.com, P Goodier <pgoodier@33themount.freeserve.co.uk>, Peter.Goodier@hse.gsi.gov.uk, sbell@ukcoal.com, Vincent.Fowler@hse.gsi.gov.uk

ATTACHED IS THE ASSEMBLY DRAWING FOR THE GR6S FLAME SAFETY LAMP WITH EMPHASIS ON THE KEY ELEMENTS OF THE GLASS PLATE.

THIS IS AN ONGOING COMMUNICATION PROCESS DESIGNED TO IMPROVE LAMP ROOM MAINTENANCE AND BUILD UP A MANUAL FOR TRAINING.

YOUR COMMENTS WOULD BE APPRECIATED.

IF YOU FEEL OTHERS SHOULD BE ADDED TO THIS LIST PLEASE CONFIRM THEIR DETAILS.

PLEASE CONFIRM YOU HAVE RECEIVED THIS EMAIL AND THE ACTION YOU HAVE TAKEN.

REGARDS DAVID MATHER
PROTECTOR

GR6S assembly drawing.pdf

Content-Type: application/pdf

Content-Encoding: base64